

Tabulka náhrad endkodérů PRECIZIKA za enkodéry jiných výrobců:

Výrobce, model	Precizika
HEIDENHAIN, Germany^{*1}	
ROD 1020	A36-F, +5 V
ROD 1030	A36-F, 10...30 V
ROD 1050	A36-A, +5 V
ROD 1080	A36-AV, +5 V
ROD 426	A58-F, +5 V
ROD 456	A58-A, +5 V
ROD 436 (HTL)	A58-F, 10...30 V
ROD 466 (TTL)	A58-F, 10...30 V
ROD 486	A58-AV, +5 V
ROD 420	A58D-F, +5 V
ROD 430	A58D-F, 10...30 V
ROD 450	A58D-A, +5 V
ROD 480	A58D-AV, +5 V
ROD 250	A110-A
ROD 260 (TTL, x1)	A110-F
ROD 270, 271 (TTL, x5)	A110-F
ROD 280	A110-AV
ROD 700, 800	A170-A, z=18000
ROD 780, 880	A170-AV, z=18000
RON 225	A90H-F ^{*2}
RON 255	A90H-A, z=9000, 18000 ^{*2}
RON 275 (TTL, x5)	A90H-F ^{*2}
RON 285	A90H-AV, z=9000, 18000 ^{*2}
RON 285C	A90H-AV, z=18000 ^{*2}
RON 705	A170H-A, z=18000 ^{*2}
RON 785	A170H-AV, z=18000 ^{*2}
ERO 1221, 1222, 1225	A42M-F
ERO 1251, 1252	A42M-A
ERO 1285	A42M-AV
LS107	L35-A ³
LS 403	L18-A
LS 406	L18T-A
LS 476	L18T-F
LS 486	L18T-AV
LS 501(D), 503(D), 505, 507	L35T-A ^{*3}
LS 701, 703, 705, 707	L35T-A ^{*3}
LS 803, 803D, 903	L18-A ^{*4}
MEGATRON Elektronik, Germany	
MOZ30	A28-F

Výrobce, model	Precizika
LARM, Czech	
IRC 110, 111	A58C2
IRC 120, 122	A58C-F
IRC 125	A58C3
IRC 300-302, 202	A58-F, 10...30 V
IRC 303-305, 205	A58-F, +5 V
IRC 307	A58-AV, +5 V
IRC 310-312	A58D-F, 10...30 V
IRC 313-315	A58D-F, +5 V
IRC 317	A58D-AV, +5 V
RSF, Austria	
MSA 6707	L18 (L18-F, L18-AV)
MSA 6717	L18B
MSA 370, 390	L35T-F
MSA 371, 391	L35-F
GIVI MISURE, Italy	
EN 500	A58
EN 536	A58D
MTS	MT
SCR 3923	L23
GMS	L50

Notes:

^{*1} Enkodéry PRECIZIKA nemají "error detection signal"

^{*2} Rozdíl v hřídelce enkodéru

^{*3} Rozdíl v rozměrech enkodéru

^{*4} It is necessary use additional gaskets because the cross section of housing and head are different.